


02/HAK/ 45 /E2


20 May 2021

The Principal
Kendriya Vidyalaya
AFS Hakimpet
Secunderabad-500014

CERTIFICATE OF SAFETY OF KV SCHOOL BUILDING

1. Ref your letter No F. 210118/KV (AFS) HPT/2021-22/ dt 19 May 2021.
2. As this office is not having requisite testing/investigation facility to certify that the School building is structurally safe and sound, it is recommended that if felt appropriate a specialized agency may be entrusted for the purpose.
3. In the visual inspection of undersigned, It is observed that, External plaster of building at some places are worn out, chajja concrete on exposed surfaces are damaged. Backside of toilet blocks external plasters are damaged. At some places superficial plaster cracks are observed. Expansion joints of the building are needed to be treated.
4. In view of the above, it is recommended that to increase the life of buildings, external plastering and plinth protection at some places to be done on priority.
5. However by visual inspection of the subject building there is no structural cracks, no unequal settlements in columns and sag in beams and columns of the building. Hence the building is safe and sound.





(P C Sambasivan)
AE (Civ)
AGE B/R (AF) Hakimpet

Copy to:-

GE (AF) Hakimpet

- for info pl.